PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No.

Date: 08/2012

Source Identification Number: 12

Description: Grey caulk at copper flashings, white/black coating on flashing, and black asphalt top of edge flashing seams.



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Date: 08/2012

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No. 2

Source Identification

Number: 9

Description: Beige caulk in CMU expansion joints.



Tighe&Bond Client Name: Town of Guilford

PHOTOGRAPHIC LOG

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No.

Date: 08/2012

Source Identification

Number: 6

Description: Grey caulk at CMU/brick wall joint



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford


Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. Date: 08/2012

Source Identification

Number: 7

Description: Grey caulk at gym window frame/sill



Tighe&Bond Client Name: Town of Guilford

PHOTOGRAPHIC LOG

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No.

Date: 08/2012

Source Identification

Number: 8

Description: Felt beneath black asphalt vents, portholes, drain pans.



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. Date: 08/2012

Source Identification Number: 14

Description: Green rubbery caulk in metal siding



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No.

Date: 08/2012

Source Identification Number: 30 & 31 &

32

Description: Courtyard overview for photos 8, 9, 10, 11 & 12



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No.

Date: 08/2012

Source Identification Number: 30 & 31

Description: Grey caulk at vent louvers



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No.

Date: 08/2012

Source Identification Number: 30 & 31

Description: Residual grey window frame caulk



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 10 Date: 08/2012

Source Identification Number: 30 & 31

Description: Concrete foundation below glazed brick wall



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No.

Date: 08/2012

Source Identification Number: 32

Description: White caulk on building seems/sills



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249


Photo No. 12

Date: 08/2012

Source Identification

Number: 32

Description: White caulk on building seems/sills



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No. 13 Date: 08/2012

Source Identification

Number: 33

Description: Dark grey caulk at building transition



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. Date: 08/2012

Source Identification Number: 39

Description: White glazing in metal window frames



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 15 Date: 08/2012

Source Identification

Number: 41

Description: Black glazing in metal window frames



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No.

Date: 08/2012

Source Identification

Number: 51

Description: Tan caulk at urinals



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No. 17 Date: 08/2012

Source Identification

Number: 53

Description: Tan caulk at CMU expansion joints



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. Date: 08/2012

Source Identification Number: 54

Description: White window/door caulk



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249


Photo No.

Date: 08/2012

Source Identification

Number: 55

Description: Hard grey expansion joint caulk



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. Date: 08/2012

Source Identification Number: 56

Description: White caulk at metal window frame



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. 21 Date: 08/2012

Source Identification

Number: 59

Description: Floor wax on gym floor



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No. 22 Date: 08/2012

Source Identification

Number: 60

Description: Tan caulk at architectural glass block



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. 23

Date: 08/2012

Source Identification

Number: 61

Description: Caulk at greenhouse



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Date:

08/2012

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. 24 A

Source Identification Number: 16

Description: Clear caulk on metal window panels and black calk at facia



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 24 B Date: 08/2012

Source Identification

Number: 16

Description: Clear caulk on metal window panels and black calk at facia seams metal



Tighe&Bond

PHOTOGRAPHIC LOG

Project No. T-0249

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Photo No. Date: 08/2012

Source Identification Number: 20

Description: Black caulk at louver



PHOTOGRAPHIC LOG

Client Name: Town of Guilford


Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 26 Date: 08/2012

Source Identification Number: 23

Description: Grey caulk at metal door/window frames and dark grey rubbery caulk at window frame



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. Date: 08/2012

Source Identification Number: 25

Description: Black caulk at sash joint and window frames and panels



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 28 Date: 08/2012

Source Identification

Number: 34

Description: Black asphalt concrete flashing



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 29 A Date: 08/2012

Source Identification

Number: 40

Description: Black glazing in metal window frames

Typical windows in 1958 construction



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 29 B Date: 08/2012

Source Identification

Number: 40

Description: Black glazing in metal window frames

Typical windows in 1958 construction



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 29 C Date: 08/2012

Source Identification

Number: 40

Description: Black glazing in metal window frames

Typical windows in 1958 construction



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 30 Date: 08/2012

Source Identification Number: 42

Description: White brittle metal window frame caulk



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford


Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. Date: 08/2012

Source Identification Number: 43

Description: White rubbery metal door frame and expansion joint caulk



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 31 B Date: 08/2012

Source Identification Number: 43

Description: White rubbery metal door frame and expansion joint caulk



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. Date: 32 A 08/2012

Source Identification Number: 45

Description: Black metal window/door frame caulk and black glazing

Typical large windows in 1968 construction



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 32 B Date: 08/2012

Source Identification Number: 45

Description: Black metal window/door frame caulk

Typical windows in 1968 construction



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. 32 C Date: 08/2012

Source Identification Number: 45

Description: Black metal window/door frame caulk

Typical windows in 1968 construction



Tighe&Bond


Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Photo No. 33 A

Source Identification Number: 47 & 48

Description: Grey/white expansion joint caulk



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT Project No. T-0249

Photo No. 33 C

Date: 08/2012

Source Identification Number: 47 & 48

Description: Grey/white expansion joint caulk



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT


Project No. T-0249

Photo No.

Date: 08/2012 34

Source Identification Number: NA

Description: **Electrical** Transformers and Vault



PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No. 35 Date: 08/2012

Source Identification Number: NA

....

Description: Electrical Transformers and Vault



Tighe&Bond

PHOTOGRAPHIC LOG

Client Name: Town of Guilford

Site Location: Guilford High School, 605 New England Road, Guilford, CT

Project No. T-0249

Photo No.

Date: 02/2013

Source Identification Number: NA

Description: Metal Flashing Installed Over Source Materials 47 and 48



Tighe&Bond **PHOTOGRAPHIC LOG** Client Name: Town of Guilford Site Location: Guilford High School, Project No. T-0249 605 New England Road, Guilford, CT Photo No. Date: 37 02/2013 Source Identification Number: NA **Description: Barriers** Installed Over Air Intakes at 1968 **Heating Units**